

Los Angeles Department of Building and Safety

The information below was found on the following address:

5637 1/2 W CORBETT ST

Parcel Profile Report:

1

Permit Information found:

3

— 5637 1/2 W CORBETT ST

Application/Permit #	PC/Job #	Type	Status	Work Description
----------------------	----------	------	--------	------------------

— 5637 1/2 W CORBETT ST 90016

Application/Permit #	PC/Job #	Type	Status	Work Description
23016 - 20000 - 15686	X23VN04642	Bldg-Alter/Repair	Permit Finaled 10/4/2023	1 Kitchen/bathroom () remodel for residential buildings (no structural changes).
23041 - 20000 - 32101	X23VN04829	Electrical	Permit Finaled 9/19/2023	REWIRE & SUB PANEL
23041 - 20001 - 32101	X23VN06063	Electrical	Issued 6/23/2023	SUPPLEMENTAL PERMIT TO ADD 8 CIRCUITS
23042 - 20001 - 10996	X23VN06073	Plumbing	Issued 6/26/2023	INSTALL NEW TOILET, NEW LAVATORY
23042 - 90000 - 20731	--	Plumbing	Permit Finaled 2/27/2024	Remove/replace gas water heater.
23042 - 20000 - 10996	X23VN04830	Plumbing	Permit Finaled 10/3/2023	BATHROOM AND KITCHEN REMODEL

— 5637 W CORBETT ST 5637 1/2 90016

Application/Permit #	PC/Job #	Type	Status	Work Description
23041 - 90000 - 46516	--	Electrical	Permit Closed 8/7/2023	Consultation

Code Enforcement Information:

0

Certificate of Occupancy Information:

0

Retrofit Program Information:

2